# **Interconnection cables for A7**



#### **OVERVIEW**

The interconnection cable set contains several cables and hoses. The cable set is used for delivering the welding power, shielding gas, cooling liquid, and control signals from the welding power source to the wire feeder. Interconnection cable sets are available in zipper bags or in corrugated sleeves.

### GAS COOLED CABLE SETS

Ordering code	Desciption	Additional info
6260449	ROBOT 70-10-GH CABLE SHOE	Zipper bag, 70 mm2, 10 m , screw connnection to wire feeder (non dix), dix connector to powersource, Gas cooled
6260458	ROBOT 70-5-GH CABLE SHOE	Zipper bag, 70 mm2, 5 m , screw connnection to wire feeder (non dix), dix connector to powersource, Gas cooled
6260484	ROBOT 70-15-GH CABLE SHOE	Zipper bag, 70 mm2, 15 m , screw connnection to wire feeder (non dix), dix connector to powersource, Gas cooled
6260480	ROBOT 70-20-GH CABLE SHOE	Zipper bag, 70 mm2, 20 m , screw connnection to wire feeder (non dix), dix connector to powersource, Gas cooled
6260483	A7 ROBOT 70-5-GH	Corrugated sleeve, 70 mm2, 5 m, cable shoe, Gas cooled

## WATER COOLED CABLE SETS

Ordering code	Desciption	Additional info
6260459	ROBOT 70-5-WH CABLE SHOE	Zipper bag, 70 mm2, 5 m , screw connnection to wire feeder (non dix), dix connector to powersource, Water cooled
6260460	ROBOT 70-10-WH CABLE SHOE	Zipper bag, 70 mm2, 10 m , screw connnection to wire feeder (non dix), dix connector to powersource, Water cooled
6260481C1	ROBOT 70-15-WH CABLE SHOE	Zipper bag, 70 mm2, 15 m , screw connnection to wire feeder (non dix), dix connector to powersource, Water cooled
6260481	ROBOT 70-20-WH CABLE SHOE	Zipper bag, 70 mm2, 20 m , screw connnection to wire feeder (non dix), dix connector to powersource, Water cooled
6260482	A7 ROBOT 70-5-WH	Corrugated sleeve, 70 mm2, 5 m, cable shoe, Water cooled

### TECHNICAL SPECIFICATIONS

#### Interconnection cables for A7

Product code See technical specifications

20092024 20092024